



SERVICE BULLETIN

Classification: EM07-002d	Reference: NTB07-088d	Date: July 30, 2010
-------------------------------------	---------------------------------	-------------------------------

2005 – 2006 350Z; ENGINE OIL LEVEL IS LOW

This bulletin amends NTB07-088c. The Service Procedure and Parts Information has changed. No other changes have been made. Please discard the previous version of this bulletin.

APPLIED VEHICLES: 2005 350Z (Z33) Track and 35th Anniversary Edition with M/T
2006 350Z (Z33) with M/T

APPLIED VIN: All VINs

APPLIED DATE: All Dates

IF YOU CONFIRM

Engine oil level is low.

OR

There is unusual engine noise.

ACTION

Use the "Repair Flow Chart" in the Service Procedure on page 2 to determine the complete repair procedures for a specific vehicle.

CAUTION: If the short engine is replaced as part of this bulletin, please advise the customer to follow the Owner's Manual "Engine Break-in Schedule" for the first 1,200 miles including:

- DO NOT RUN THE ENGINE OVER 4,000 RPM.
- DO NOT ACCELERATE AT FULL THROTTLE.

NOTE: Check OBD-II "Engine" Self Diagnosis for any stored DTC codes and use the appropriate Electronic Service Manual (ESM) to repair any DTC code found stored.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.