

Firestone Complete Auto Care
999 Woodbridge Center Dr.
Woodbridge, NJ. 07095

Name
 Address

Home Tel.:

VIN:

License:


Technician:

Mileage:



Time Printed 4/17/12 5:05 PM

Nissan : 350Z : 2003-05 : with 18" Wheel
 Before Measurements

Left Front




Right Front




- Excessive Camber could cause shoulder wear.
- Negative Camber could cause road shock or poor ride quality.
- Excessive Toe could cause scuffing or shoulder wear.

Left Rear



Right Rear



Thrust Angle

- Excessive Camber could cause shoulder wear.
- Excessive Toe could cause scuffing or shoulder wear.

Firestone Complete Auto Care
999 Woodbridge Center Dr.
Woodbridge, NJ. 07095

Name
 Address

Home Tel.:
 VIN:

License:
 Technician:

Mileage:
 Time Printed 4/18/12 2:03 PM

Nissan : 350Z : 2003-05 : with 18" Wheel

