

# X-Y Plot of power,torque,BOOST,LM1\_O2-RPM

C:\Documents and Settings\Drags 12\_14\_14\Hp Test 3rd gear run 4.log - 3rd Gear

RPM (RPM)	power (hp)	torque (lbft)	BOOST (PSIg)	LM1_O2 (AFR)
5400	397	386.0	10.18	11.33
5410	393	381.6	10.35	11.94
5440	404	390.4	10.48	12.08
5470	412	395.7	10.65	11.95
5510	423	403.1	10.83	11.91
5560	432	408.9	11.00	11.57
5610	443	414.6	11.21	11.41
5660	452	419.4	11.43	11.45
5710	461	424.2	11.64	11.77
5770	470	427.8	11.86	12.02
5820	478	431.3	12.08	12.17
5880	486	434.4	12.33	12.07
5930	493	437.0	12.59	12.04
5990	500	438.8	12.85	11.98
6050	508	440.5	13.11	12.11
6100	513	441.8	13.33	12.14
6160	520	443.2	13.59	12.02
6210	525	444.0	13.84	12.02
6270	532	445.3	14.10	12.01
6320	537	446.2	14.36	12.22
6380	543	447.1	14.62	12.20
6430	547	447.1	14.88	12.23
6490	554	448.0	15.18	12.41
6540	558	448.4	15.44	12.41
6590	564	449.3	15.74	12.45
6640	568	448.9	16.00	12.26
6700	574	449.7	16.00	12.39
6750	569	442.3	16.00	12.49
6800	563	434.8	16.00	12.70
6850	570	437.4	16.00	12.79